#### CALIBRATION GUIDE



**IMPORTANT:** Read Before Using.

## UNEEKOR



# **Calibration Guide**

# How to calibrate your QED sensor after installation.





## UNEEKOR





Step 1: Open the "This PC" app.

Step 2: Click the Local Disk (C:) Drive.

Parts There	Cor Cor Chananter International International Internationa	And	
1 <u>1</u>	PC + 10 (Cp +	- A - D - See Mark	
Contras Dantas A Dantas A Dant	App Def Def Nature Fertups Fertups Fertups(App) (0)(2)(2)(2) (0)(2)(2)(2) (0)(2)(2)(2) (0)(2)(2)(2) (0)(2)(2)(2) (0)(2)(2)(2) (0)(2)(2)(2)(2)(2)(2)(2)(2)(2)(2)(2)(2)(2)	AUDECTIV         10 Andree           AUDECTIV         10 Andree	
Coming and	ZXAM Anton	TOLEND LOT ME Lawrence	
Codia Doda Doda Doda Doda Doda Doda Doda Dod	in and the	14	

Step 3: Click the "Z3CAMSensor" folder.





Cash (say from )	Lar Langet Lange	× =	in dem *	Const Constant	
- + + 🖬 + The	R + (S40) + Disklamas	r			
	No.	Extrinsitien :	Travel	the later	
Goldk exten	C MTMTA	A COLUMN 2 NO 14	Translation .		
Erany /	There is a second	7 15, 2218 4 (2018)	Frank Damage	2.44	
Dyurfamik /	E linemetry	10/2010 1/17/044	They Designation	148	
Courses r	1 hitse	An Address of Address of Mark	That Document	1.00	
the sector	A MetworkCooks	1127912344	Indiates	10.01	
Guides	S sparter, rath 4003-at	Sinching waters	A Auglication server.	342.48	
there bee	approx, resulting	STREET AVAILABLE	Application assess	1,764.03	
A summer	Spence, spence, aprendition, at	1010/001113/00-M	d Application where	1.002 100	
the local data in the	appress, hippigate at	biolog many	A Application taken.	751-08	
means open	approved to propulation	184ppert set al	A Application servers.	1,014.102	
Courtine Claud Neu	Superior, regenulation	2102010101000	d Jophanizarian	6,213,930	
durbin .	E samo, manual take	1012/07/2004	A Application process	1.01110	
Concerne .	6 son	4/02/010 11/1/14	A Technologies	3.42	
764.15	the words	1/10/01/02/01/04	1 Supplement	-39-KE	
30 Objects	at 22CMM Server	1100018-00094	- eignal (Rafford	.1.48	
Course.	Wislow	2-94(010.032AH	Application	1,279.48	
1 Description	alars .	ACTIVATION OF A DESIGN AND	H Samplaumi Japp.	1,001.00	
	22CM/_Alt+49en	5/10/219 422.416	Application	1,000-18	
- torrent.	RE TOCING Marches	51420914146	Application	10,710.40	
Mar C	E INCHAR FOR	Nie mit to av	- Application	11,737.48	
E Feture	TICHN, TOOK	Pile Incorption 31,Mil,1000.	"  Siegrand inst	1.000 KB	
Trates	E sicen-idential	Company Coetton	Application Internal	5.412.41E	
2 55000	I chanidant wange	File operation of \$12.2	Apply must	00.42	
a mining	Telephone, subscription	Sec (5.1.68	Application	10.49	
- model	E plcan-Idantik di	100011010	7 Application enters	10.48	
	A Diardheat	2121-2214 - 444-814	Toph must	1,046,422	
	22CarrCons.08	2-30-329 10-69	Septembers.	6.452.48	

Step 4: Inside "Z3CAMSensor" find and run the "Z3\_CAM\_TOOL"



Step 5: Inside the "Z3\_CAM\_TOOL" Make sure the status are all green. (If status is not green please contact support@uneekor.com)

#### Step 6:

Check the "Center Cam" and "Side Cam." Make sure they are on. Adjust brightness if needed. If you do not see anything, please refer to our firewall settings guide in the install link.



### UNEEKOR







(Make sure your hitting mat is level! If not you will get inaccurate shot data)

Hitting Screen



#### Step 7:

If steps 5 and 6 passed, place the calibration chart on the hitting mat. Make sure the center line on the chart is straight on the "center cam" ONLY.

#### Step 8:

It is important the center line is straight and circle tee position is closer towards the back away from the hitting screen. See diagram.

#### Step 9:

Then click the "Calibration" button. You will see some things happening in both cameras. Please wait until you get a message.











Step 10: If calibration is successful you will see this message. Click the "Confirm" button (If calibration failed please contact support@uneekor.com)

#### Step 11:

After you click confirm check to see if you see a grid of green dots on both cameras. Then move onto "Area Setting."

#### Step 12 :

In the "Area Setting" menu, you will see this. In here you are able to click and drag the green box to adjust your hitting zone. The box must stay within the green dots. and close to center.





Step 13 : Make sure the "One Area Mode" is on.

Step 14 : Click the "Confirm" button.

Step 15 : Then on the next page click the "Confirm" button. You are finished with calibration.







#### **POWER FOR EVERY GOLFER**

Uneekor, Inc.

26249 Enterprise Court Lake Forest, CA 92630

Tel: 1-949-328-7790

sales@uneekor.com

support@uneekor.com