




Ventilation Assessment Summary

Ventilation Assessment



#	HVAC		Site		Air Changes				Halo	OR	PAC	
	Room	Type	Campus	Building	Target	Actual	Result	Min. CADR	120 cfm		100 cfm	300 CFM
1	C213	Classroom	College of Alameda	C	4	4.0	Meets target	cfm				
2	C212	Classroom	College of Alameda	C	3	12.3	Meets target	cfm				
3	C211	Classroom	College of Alameda	C	5	15.1	Meets target	cfm				
4	C210	Classroom	College of Alameda	C	3	12.5	Meets target	cfm				
5	C209	Classroom	College of Alameda	C	4	18.7	Meets target	cfm				
6	C208	Classroom	College of Alameda	C	4	18.7	Meets target	cfm				
7	C204	Lobby	College of Alameda	C	3	27.9	Meets target	cfm				
8	C205	Office	College of Alameda	C	3	9.3	Meets target	cfm				
9	C206	Office	College of Alameda	C	3	13.5	Meets target	cfm				
10	C207	Office	College of Alameda	C	3	18.9	Meets target	cfm				
10	C203	Office	College of Alameda	C	3	21.9	Meets target	cfm				
11	C202	Office	College of Alameda	C	3	19.1	Meets target	cfm				
12	C113	Classroom	College of Alameda	C	3	16.3	Meets target	cfm				
13	C201	Office	College of Alameda	C	3	16.2	Meets target	cfm				
14	C113A	Office	College of Alameda	C	3	15.3	Meets target	cfm				
15	C104	Classroom	College of Alameda	C	3	2.1	Does not meet target	cfm	2		1	
16	C103	Break room	College of Alameda	C	3	4.1	Meets target	cfm				
17	C105	Classroom	College of Alameda	C	4	10.1	Meets target	cfm				
18	C106	Office	College of Alameda	C	3	25.6	Meets target	cfm				
19	C107	Office	College of Alameda	C	3	1.3	Does not meet target	cfm	1		1	
20	C109	Classroom	College of Alameda	C	3	9.1	Meets target	cfm				
21	C110	Office	College of Alameda	C	3	16.1	Meets target	cfm				
22	C112	Classroom	College of Alameda	C	3	2.7	Does not meet target	cfm	1		1	
23	C111	Science Lab	College of Alameda	C	3	0.0	Does not meet target	cfm	1		2	